








Section
Schnitt B-B



Kontakfläche zum Kettenglied farbfrei und metallisch sauber halten.
contact surface to the chain link must be free of paint and kept metallically clean.

Achtung !
Einzelglied II in einer Vorrichtung geheset
und geschweisst.

single link tack welded and welded being mounted in a corresponding device.

Abnahmeamt
 Acceptance of inspection

MAT:St-52

duration without tolerance date mean QM 7148	before date in 100-400 500 measuring rate of roughness by sec. by 200 cm/s
--	---

[illegible]

Year	Number of people
1967	150
1968	175
1969	200
1970	225
1971	250
1972	275